

Oil Field Environmental Incident Summary

Incident: 20160302072850

Date/Time of Notice: 03/02/2016 07:28

Responsible Party: Dynamic Support Services

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: KING 1-5H

Field Name: OLIVER

Well File #: 21027

Date Incident: 3/1/2016

Time Incident: 15:30

Facility ID Number:

County: WILLIAMS

Twp: 157

Rng: 98

Sec: 5

Qtr:

Location Description:

Submitted By: Shane Knuchel

Received By:

Contact Person: Shane Knuchel
5401 Hwy 8
Stanley, ND 58784

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels	2.5	Barrels	3	barrels
Brine	2	Barrels	1.5	Barrels	2	barrels

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 9/15/2016

Clean Up Concluded: 3/2/2016

Risk Evaluation:

None

Areal Extent:

All fluid contained within dike

Potential Environmental Impacts:

Well site soil

Action Taken or Planned:

Well was shut in and tank sucked down. Standing fluid was sucked up and impacted material will be removed and replaced with clean material.

Wastes Disposal Location: TBD

Agencies Involved: Notified Gunner Harms NDIC by phone on 3/2/2016 at 7:15 AM CT

Updates

Date: 3/2/2016 **Status:** Reviewed - Assigned to Other Agency **Author:** Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained on location. NDIC retains oversight.